
GIS REGISTRY INFORMATION

SITE NAME:	Mobil Oil #0	5-LJJ										
BRRTS #:	03-41-00369	91					FID	N-600				
COMMEDOE #	50000 5700						(if a	ppro	priate	e):		
COMMERCE #	53209-5730	-10										
(if appropriate):												
CLOSURE DATE:	August 17, 2											
STREET ADDRESS:		npton	Ave									
CITY:	Milwaukee											
SOURCE PROPERT		RDINA	ATES	X =	68829	7			Y =	2945	20	
(meters in WTM91 pro				1		Ja			-		- Control	
CONTAMINATED ME			roundwater	_		Soil	⊢		Bot		X	
OFF-SOURCE GW C		THE RESERVE AND ADDRESS.			Yes	200	Х		No			
 IF YES, STREET. 	ADDRESS:	4827	N. Green E	Bay F	Road, M	lilwauke	е					
 GPS COORDINAT 	TES	X = 6	688304				Y =	294	1535			
(meters in WTM91 pro	THE RESIDENCE OF THE PARTY OF T											
OFF-SOURCE SOIL				Yes	3		No	X				
>Generic or Site-Spe	The state of the s		_):									
 IF YES, STREET 							120					
GPS COORDINAT		X =					Y =					
(meters in WTM91 pro		1/ 5 3/	N				11.					
CONTAMINATION IN	RIGHT OF	VAY:		ITC N	IEEDE	D	No		-			_
December 1997		aneway out	DOCUMEN	1151	NEEDE	ט						100
Closure Letter, and any cor	nditional closure	letter i	ssued									Х
Copy of most recent deed,	including legal d	escrip	tion, for all affe	ected p	ropertie	S						х
Certified survey map or rel	evant portion of	he rec	orded plat map	(if ref	erenced li	n the legal o	descrip	tion) f	or all a	ffected	d properties	х
County Parcel ID number, i	f used for county	, for al	I affected prop	erties								Х
Location Map which outlines parcels to be located easily (8.5 potable wells within 1200' of the	x14" if paper copy).	contami If grour	inated site bound ndwater standard	aries or s are ex	USGS top ceeded, th	pographic m ne map mus	ap or pl	at maj iclude	o in suff the loca	iclent de ation of	etail to permit th all municipal ar	e X d
Detailed Site Map(s) for al wells and potable wells. (8.5x14 way in relation to the source pro exceeding ch. NR 720 generic or	", if paper copy) The perty and in relation	is map	shall also show th	ne locat	ion of all c	ontaminated	public	streets	, highw	ay and	railroad rights-c	f-
Tables of Latest Groundwa	iter Analytical Re	sults (ı	no shading or	cross-	hatching)						Х
Tables of Latest Soil Analy	tical Results (no	shadir	ng or cross-hat	ching)	M							Х
Isoconcentration map(s), in and extent of groundwater conta	f required for site mination defined. If	<i>inves</i> not ava	tigation (SI) (8 ilable, include th	.5x14* i e lates	f paper co t extent of	py). The iso contamina	nt plun	tration ne map	map s	hould ha	ave flow direction	n X
GW: Table of water level e	levations, with s	amplin	g dates, and fr	ee pro	duct not	ed if prese	nt					X
GW: Latest groundwater f is greater than 20 degrees)		nitorin	g well location	map	(should b	e 2 maps	if max	imun	varia	tion in	flow direction	nχ
SOIL: Latest horizontal ex		ation e	xceeding gene	ric or	SSRCLs,	with one	conto	ır				X
Geologic cross-sections, i	f required for SI.	(8.5x1	4' if paper copy)	Ř								Х
RP certified statement that	legal description	ns are	complete and	accura	te.							х
Copies of off-source notific	257											Х
Letter informing ROW own	er of residual co	ntamin	ation (if applic	able)(public, hi	ghway or	railroa	d RO	W)			х
Copy of (soil or land use)								_				



TDD #: (608) 264-8777 Fax #: (414) 220-5374 Jim Doyle, Governor Cory L. Nettles, Secretary



August 17, 2004

Mr. Jeffrey Johnson ExxonMobil Refining & Supply PO Box 874 Joliet, IL 60434-0874

RE: Final Closure

> Commerce # 53209-5730-10 WDNR BRRTS # 03-41-003691 Mobil Oil #05-LJJ, 1710 West Hampton Avenue, Milwaukee

Dear Mr. Johnson:

The Wisconsin Department of Commerce (Commerce) has received all items required as conditions for closure of the site referenced above. This case is now listed as "closed" on the Commerce database and will be included on the Wisconsin Department of Natural Resources (WDNR) Geographic Information System (GIS) Registry of Closed Remediation Sites to address residual soil and groundwater contamination. It is in your best interest to keep all documentation related to the environmental activities that were conducted.

If residual contamination is encountered in the future, it must be managed in accordance with all applicable state and federal regulations. If it is determined that any remaining contamination poses a threat, the case may be reopened and further investigation or remediation may be required.

Thank you for your efforts to bring this case to closure. If you have any questions, please contact me in writing at the letterhead address or by telephone at (414) 220-5361.

Sincerely.

Monica L. Weis Hydrogeologist

Site Review Section

Ms. Cynthia Draves, Handex of Wisconsin

Mr. William Elliot, Lakeside Oil Company, 555 West Brown Deer Road, Suite 200, Fox Point, WI 53217

Case File

Milwaukee, Wisconsin 53212-3963 TDD #: (608) 264-8777 Fax #: (414) 220-5374 Jim Doyle, Governor

Cory L. Nettles, Secretary



June 22, 2004

Mr. Jeffrey Johnson ExxonMobil Refining and Supply Company Joliet Refinery, Administration Building, Room 260 Interstate 55 and Arsenal Road Channahon, IL 60410

RE:

Conditional Case Closure

Commerce # 53209-5730-10 WDNR BRRTS # 03-41-003691 Mobil Oil #05-LJJ, 1710 West Hampton Avenue, Milwaukee

Dear Mr. Johnson:

The Wisconsin Department of Commerce (Commerce) has reviewed the request for case closure prepared by your consultant, Handex of Wisconsin, for the site referenced above. It is understood that residual soil and groundwater contamination remains on-site. Commerce has determined that this site does not pose a significant threat to the environment and human health. No further investigation or remedial action is necessary.

The following condition must be satisfied to obtain final closure:

 All groundwater monitoring wells must be properly abandoned and the appropriate documentation submitted to me at the letterhead address.

This letter serves as your written notice of "no further action". Timely filing of your final PECFA claim (if applicable) is encouraged. If your claim is not received within 120 days of the date of this letter, interest costs incurred after 60 days of the date of this letter will not be eligible for PECFA reimbursement.

Thank you for your efforts to protect Wisconsin's environment. If you have any questions, please contact me in writing at the letterhead address or by telephone at (414) 220-5361.

Sincerely,

Monica L. Weis Hydrogeologist

Site Review Section

cc: Ms. Cynthia Draves, Handex of Wisconsin

Case File

REGISTER'S OFFICE | SS Milwaukee County, WI

RECORDED AT 2:40 PM

01-16-2003

JOHN LA FAVE REGISTER OF DEEDS

AMOUNT 21.00

Recording Area

Name and Return Address:

Stewart Title Guaranty Company 1980 Post Oak Blvd., Suite 610 Houston, TX 77056

ATTN: Jackie Trainor

National Title Services

205-0124-100-9

Parcel Identification Number (PIN)

TRANSFER \$ 2124,00 FEE

SPECIAL WARRANTY DEED

Document Title:

Document Number:

REEL

IMADI

488

THIS INSTRUMENT WAS DRAFTED BY: Paul H. Ryan – (703) 846-2348

45

SPECIAL WARRANTY DEED

THIS SPECIAL WARRANTY DEED is between ExxonMobil Oil Corporation, a New York corporation, called "Grantor", and LakePointe Holdings, LLC, a Wisconsin Limited Liability Company, called "Grantee", whose mailing address is 555 West Brown Deer Road, Suite 200, Fox Point, WI 53217.

Grantor, for a good and valuable consideration, grants, bargains, sells and conveys with Limited Warranty to Grantee all of the real property (the "Property") described in Exhibit "A," attached hereto and made a part hereof. The Property is NOW KNOWN AS the property described in Exhibit "B", attached hereto and made a part hereof.

This conveyance is made expressly subject to:

- 1. Encroachments, protrusions, easements, changes in street lines, rights-of-way and other matters that would be revealed by a current on the ground survey and inspection of the property.
- 2. Recorded leases, agreements, easements, rights of way, covenants, conditions and restrictions as the same may be of present force and effect.
- 3. Zoning regulations, ordinances, building restrictions, and regulations and any violations thereof.
- 4. The lien for real property taxes for the current year, and any liens for special assessments which as of the date hereof are not due and payable; and
- 5. Rights of any franchisee, subtenant or licensee of Grantor occupying the Property, pursuant to a valid lease, license or other occupancy agreement, at the Closing Date (as such term is defined in the Agreement of Purchase and Sale dated November 21st, 2002, by and between the Grantor and Grantee herein).

TO HAVE AND TO HOLD the Property, together with the appurtenances, estate, title and interest thereto, unto Grantee, Grantee's successors, heirs and assigns forever, subject to the provisions hereof, and in lieu of all other warranties, express or implied, Grantor does hereby bind itself, its successors and assigns, to warrant and forever defend the title to the Property unto Grantee, Grantee's successors, heirs and assigns, against every person whomsoever lawfully claiming or to claim the same or any part thereof, by, through or under Grantor, but not otherwise.

IN TESTIMONY WHEREOF, Grantor has hereunto set its hand and seal this day of

January, 2003, with an effective date of	n. 16 ^T , 2003.	
Witness:	ExxonMobil Oil Corporation, a PIFF New York corporation	
Name: D. J. Rasmussen D. J. Rasmussen D. D. Rasmussen	By:	REEL
Name: D. DAgostino. D. D'Agostino.		5491
(Corporate Seal)	LakePointe Holdings, LLC A Wisconsin Limited Liability Company By Lakeside Oil Company, Inc.	&
Attest:	A Wisconsin Corporation The Managing Member By:	MAGE
	Name: William Elliott Title: President	
COMMONWEALTH OF VIRGINIA)		4883
) ss COUNTY OF FAIRFAX)	: · ·	
On this <u>9</u> day of January, 2003, being by me duly sworn, did depose an ExxonMobil Oil Corporation , a New York the foregoing instrument pursuant to a Sp recorded immediately prior hereto in Deed	before me personally came D. J. Fisher, to me known, who d say that deponent is the Agent and Attorney-in-fact for a corporation, the corporation described in and which executed ecial Power of Attorney executed on December 16th, 2002, Book, Page (as Instrument # \$43152); and to by like order on behalf of said corporation.	,
	Notary Public - Dorothy M. Morris	
My Commission Expires: 4/30/2003		

/Lakeside Special Warranty Deed-final

2

STATE OF WISCONSIN) COUNTY OF MILWAUKEE

This instrument was acknowledged and executed before me this 5th day of January, 2003, by William Elliott, who acknowledged himself to be the President of Lakeside Oil Company, Inc., a Wisconsin Corporation, the Managing Member of LakePointe Holdings, LLC, a Wisconsin Limited Liability Company, the limited liability company described in the foregoing instrument and that he was authorized to execute the same.

> Notary Public, State of Wisconsin Commission

My

器

ထ

NECT.

8645

4885

EXHIBIT "A" TO SPECIAL WARRANTY DEED

PROPERTY DESCRIPTION

Site # 13238 1708 West Hampton Avenue a/k/a 4803 N Green Bay Ave. Our File # 02161075

The East 51.35 feet of the West 191.35 feet of Lot 5, except the South 22 feet thereof, in Block 1, in Lincoln Park Annex, being a part of the Southeast Quarter (SE1/4) of Section 31, in Township 8 North, Range 22 East, in the City of Milwaukee, Milwaukee County, State of Wisconsin.

ALSO Lot 5, in Block 1, in Lincoln Park Annex, being a part of the Southeast Quarter (SE1/4) of Section 31, in Township 8 North, Range 22 East, in the City of Milwaukee, except the West 191.35 feet thereof.

Also that part of the Southeast Quarter (SE1/4) of Section 31, in Township 8 North, range 22 East, in the City of Milwaukee, bounded and described as follows, to-wit: Commencing at a point in the South line 1227.35 feet East of the Southwest corner of the Southeast Quarter (SE1/4) of Section 31, running thence East on and along the South line of the Southeast Quarter (SE1/4) of Section 31, 208 feet to a point at the intersection of the center line of North Green Bay Avenue with the South line of said 1/4 Section; thence North 10° 43' West on and along the center line of North Green Bay Avenue 140.46 feet to a point; thence West on and along a line which is 138 feet North of and parallel with the South line of said 1/4 Section 182.81 feet to a point; thence South 138 feet to the place of beginning, excepting therefrom the following described premises:

- (1) The South 33 feet thereof lying Westerly of the Westerly line of North Green Bay Avenue:
- (2) That portion of said premises bounded and described as follows: Commencing at a point in the South line of the Southeast Quarter (SE1/4) of Section 31, in Township 8 North, Range 22 East, said point lying 1227.35 feet East of the Southwest corner of said 1/4 Section: running North and parallel to the West line of said 1/4 Section 33.00 feet to a point in the North line of West Hampton Avenue, said point being the point of beginning of the land to be described: thence North on a line parallel to the West line of said 1/4 Section 22.00 feet to a point, which is 55.00 feet North of and measured at right angles to the South line of said 1/4 Section; thence East on a line parallel to the South line of said 1/4 Section 152.45 feet to a point; thence Northeasterly on a line 15.32 feet to a point in the Westerly line of North Green Bay Avenue, said point being 34.39 feet Northwesterly of the North line of West Hampton Avenue and measured along the Westerly line of North Green Bay Avenue; thence Southeasterly along said Westerly line of North Green Bay Avenue; thence Southeasterly along said Westerly line of North Green Bay Avenue; thence Southeasterly along said Westerly line of North Green Bay Avenue; thence West along said North line of West Hampton Avenue; thence West along said North line of West Hampton Avenue 168.47 feet to the point of beginning;
- (3) That portion of said premises lying within the limits of North Green Bay Avenue.

The East 51.35 feet of the West 191.35 feet of Lot 5, except the South 22 feet thereof, in Block 1, in Lincoln Park Annex, being a part of the Southeast Quarter (SE 1/4) of Section 31, in Township 8 North, Range 22 East, in the City of Milwaukee, Milwaukee County, State of Wisconsin.

ALSO Lot 5, in Block 1, in Lincoln Park Annex, being a part of the Southeast Quarter (SE 1/4) of Section 31, in Township 8 North, Range 22 East, in the City of Milwaukee, except the West 191.35 feet thereof.

ALSO that part of the Southeast Quarter (SE ¼) of Section 31, in Township 8 North, Range 22 East, in the City of Milwaukee, bounded and described as follows, to-wit: Commencing at a point in the South line 1227.35 feet East of the Southwest corner of the Southeast Quarter (SE ¼) of Section 31, running thence East on and along the South line of the Southeast Quarter (SE ¼) of Section 31, 208 feet to a point at the intersection of the center line of North Green Bay Avenue with the South line of said ¼ Section; thence North 10%%d43' West on and along the center line of North Green Bay Avenue 140.46 feet to a point; thence West on and along a line which is 138 feet North of and parallel with the South line of said ¼ Section 182.81 feet to a point; thence South 138 feet to the place of beginning, excepting therefrom the following described premises:


- (1) The South 33 feet thereof lying Westerly of the Westerly line of North Green Bay Avenue:
- (2) That portion of said premises bounded and described as follows: Commencing at a point in the South line of the Southeast Quarter (SE ¼) of Section 31, in Township 8 North, Range 22 East, said point lying 1227.35 feet East of the Southwest corner of said ¼ Section; running North and parallel to the West line of said ¼ Section 33.00 feet to a point in the North line of West Hampton Avenue, said point being the point of beginning of the land to be described; thence North on a line parallel to the West line of said ¼ Section 22.00 feet to a point, which is 55.00 feet North of and measured at right angles to the South line of said ¼ Section; thence East on a line parallel to the South line of said ¼ Section 152.45 feet to a point; thence Northeasterly on a line 15.32 feet to a point in the Westerly line of North Green Bay Avenue, said point being 34.39 feet Northwesterly of the North line of West Hampton Avenue and measured along the Westerly line of North Green Bay Avenue; thence Southeasterly along said Westerly line of North Green Bay Avenue 34.39 feet to a point in said North line of West Hampton Avenue; thence West along said North line of West Hampton Avenue; thence West along said North line of West Hampton Avenue; thence West along said North line of West Hampton Avenue 168.47 feet to the point of beginning.
- (3) That portion of said premises lying within the limits of North Green Bay Avenue.

BENGA PARIFOF THE SOUTH CAST & SECTION 2)

TOWN BINDETHEAMSE 22 CAST

TOWN ** COUNTY OF MILWAUKEE STATE OF WISCONSIN

SCALE 1 INCH = 100 FEET



STATE OF Wisconsin COUNTY OF MILWAUKEE

1, 5.D. Austin, Surveyor, do hereby certify that I have evrueyed and mapped "Lincoln Park Annex" being a part of the Bouth-east One-quarter (5.15/4), Section Thirty-one (31), Town Kight (6), North Range Twenty-two (22) Keet,

Town of Milwanker, County of Milwanker, State of Misconsin, bounded and described as follows, to-wit:-

"Commencing at the couldwest country of the Southeast One-quarter (5.E.14), Section Thisty-one (31), Town Right (B) Horth, Range Twenty-two (22) Rast, sunning thence nouth on and along the west line of the South-east One-quarter (BK.14), Section Thirty-one (31), Six Hundred and Sixty-Hires and Seventy-five Hundredth; (663.75) feet to a point; thence Tast on and along a fine which is 5ix Hundred and Sirty-three and Soventy-five Hundredths (663.75) feet north of and paraflet with the south line of said One-quarter section, One Thousand Three Hundred and Seven and Seventy-nine Hundredtho (1307.79) feet to a point in the center line of Greenbay Avenue; thence south Ten Degrees and Forty. Herea Minutes (10 48) Kash on and along the center line of Arcenbay Avenue, Five Hundred and Thirty-five and six Hundredthe (635.06) feet to a point which is One Hundred and Thirty-eight (198) feet north of the south line of the said one-quarter section; thence west on and along a line which to One Hundred and Thirty-eight (138) feet north of and parallel with the south line of said one-quarter section, One Hundred and Kighly-two and Kighty-one Hundredthe (182.01) feet to a point thence south One Hundred and Thirty-cight (198) feet to a point in the south line of the soid One. quarter section; thence west on and along the south line of the said one-quarter section, One Thousand Two Hundred and Twenty-seven and Thirty-five Hundredthis (1227.38) feet to the place of beginning. That I made such survey and the within map by order of havene & Magner; that the within may is a correct regrescritation of all exterior boundaries of the land surveyed and the divisions therein made; that in surveying, subdividing and mapping I fully complied with the provisions of Chapter 101 and Section 2261 and its amendments of the statutes retaling to plats.

milwauhee may 11th 1817

5.D. Austin Burveyor.

STATE OF WISCONSIN] COUNTY OF MILWAUKEE

5.D. Austin being first duly sworn on oath devoses and says that he to the surveyor who signed the jorgaphy costificate and that he now seems and that all the contents of the same was that all the contents of the same was true and that

he makes this afficiants as required by law. subscribed and sworn before me this 11th day of may 1917. Kloic Luckben

Hotory Public, Milwanker County, Wis. my Commission expires Hovember Sed 1918.

S.D. Austin

STATE OF WISCONSIN SS

I, the undersigned owner of "hincoln Park Annex" as mayed and platted in the within may, so hereby certify that I have consed the said land owned by me to be surveyed and platted as represented

in the foregoing cartificate of S.D. Austin, Surveyor. In withness whereof I have hereunto set my hand and seal this 11 19 day of may 1917, In gresence of

martitta Voltrath Charles A. Wagner

hovent F. Wagner BEAL

STATE OF WISCONSIN] COUNTY OF MILWAUKEE \$5

named hovens V. Wagnes to me known to be the yeapon who executed the foregoing instrument and acknowledged the same



Charles A. Wagner. notary Public, milwoules County, Wie ly Commission expires Sept RSYD 1917 city clerk

Mayor 341 6 1917 P.F. Heuch, City Clerk. TIBIT Sur Tues Daniel W. Hoan.

By Ald. Szczeckinski

PL4. # 13000

Referred to the Committee on Public Blogs + Ger unds and Public hand Commission

may 21, 1917

ALD SZCZERBINSKI presented the following:

File number 18000, milwaukes, July 2nd, 1917,

To the Honorable The Common Council of the City of Milwaukee;

gentlemen The undersigned, the Committee on Public Buildings and Grounds to which was reserved the may himself Park Anner, being a gast of the Sould Kast quarter Section 31, Town 8 north, Range 22 Kest Town and County of milwauhes, State of Wisconsin, has examined the same and respectfully recommend the adoption of the annexed resolution.

Anthony Szczer Lineki Geo. 3. Herensann Robert 3. Kamps. 8. Thompson

File number 18000

Resolved, That the may of hincoln Parti Annes, deing a yarr of the South Kast 14, Section 31, Town 8 Howler Range 22 Root Town and County of Milwauhee, state of Wisconsin, he and the same is stevely approved by the Common Council.

Maintenance consent Ald presentings, this time greenled the following From the board of Public hand Commissioners

File number 18000

June 21, 1917

Gentlement Mached Assembly, File # 19000 being a plat of hincoln Park Annew, segarand to this Board. At a meeting hald on June 1914, the Board of Pullie Land Commissioners recommend the approved of said plat. Respectfully |

BOARD OF PUBLIC LAND COMMISSIONS

Geo. N Stant () Servetary.

n youth annex, being a poor of the positions 14, section 31, town 8 north, can go east, town milworks in the county of milwounce, state of Misconsta, be and the some to hereby approved by the board of suggestions of Milwonie county

OFFICE OF THE COUNTY CHERK


milwoukes, July 15 1917

there have all filled that the foregoing in a true lond covert copy of a resolution adopted by the Board of Super-e of Millounkie County of the Andread protting continued of said Board Held on the 10 th day of July 1917





REVISIONS DATE BY CHKD



SCHEMATIC OF SURROUNDING AREA NOT TO SCALE

SCALE 1:24000

1 MILE 3000 4000 5000 6000 7000 FEET 0 1 KILOMETER WISCONSIN (

MILWAUKEE QUADRANGLE
MILWAUKEE, WISCONSIN
7.5 MINUTE SERIES (TOPOGRAPHIC)



QUADRANGLE LOCATION

EXXON MOBIL OIL CORPORATION

Safety, Health, Environment

Exxon Mobil Environmental Remediation - U. S. Retail

SITE LOCATION MAP

MOBIL SERVICE STATION # 05-LJJ

1710 WEST HAMPTON AVENUE
MILWAUKEE, MILWAUKEE COUNTY, WISCONSIN

	DRAWN BY:	M. SMITH
i	CHECKED BY:	_
	SCALE:	AS NOTED
i	DATE:	3/12/02
	DRAWING FILE:	116886

FIGURE




TABLE 1 SOIL LABORATORY ANALYTICAL RESULTS - (PVOC, Lead, GRO, DRO)

Mobil Service Station 05-LJJ Milwaukee, Wisconsin

Boring & Sample	Sample Date	Depth (ft bgs)	PID (IUs)	Percent Total Solids	Benzene (µg/kg)	Toluene (μg/kg)	Ethyl- benzene (µg/kg)	Total Xylenes (µg/kg)	MTBE (μg/kg)	1,2,4 TMBs (μg/kg)	1,3,5 TMBs (μg/kg)	DRO (mg/kg)	GRO (mg/kg)	Lead (mg/kg)
MW-1	11/18/1992	7-9		90.4	<5.5	<5.5	<5.5	14	<5.5	14	10		<10	3.03
MW-2	11/17/2003	9.5-11.5		87.0	<110	5,200	22,000	85,000	4,000	150,000	51,000		5,000	15.40
MW-3	11/18/1992	9.5-11.5		89.2	<5.6	<5.6	<5.6	<16.6	<5.6	<5.6	<5.6		<10	8.11
MW-4	11/18/1992	7-9		82.1	<6.1	<6.1	<6.1	<18.1	<6.1	12	<6.1		<10	7.90
SB-1	11/17/1992	9.5-11.5		88.6	4,200	5,800	12,000	43,700	560	20,000	5,900		1,500	10.1
SB-2	11/17/1992	9.5-11.5		85.4	17	<5.8	14	<17.8	<5.8	12	<5.8		35	5.25
SB-3	11/17/1992	9.5-11.5		87.3	<57	<57	880	24,200	10,000	56,000	9,500		7,800	16.6
SB-4	11/18/1992	7-9		95.1	<5.3	<5.3	31	520	<5.3	560	250		19	3.4
E-1	02/25/1993	8-10		95.0	<2700	<2700	11,000	36,000	<2700	55,000	8,000		1,700	<2.1
E-2	02/25/1993	8-10		88.0	<5.6	21	93	250	<5.6	220	25		45	<2.3
E-3	02/25/1993	8-10		92.0	<2700	36,000	42,000	150,000	<2700	99,000	17,000		2,000	<2.2
E-4	02/25/1993	8-10		92.0	<540	610	5,000	12,000	<540	12,000	1,800	;	270	<2.2
E-5	02/25/1993	8-10		89.0	4.7	7.8	<1.1	<2.2	<1.1	<1.1	<1.1		<5.0	<2.2
E-6	02/25/1993	8-10		87.0	5.0	7.4	<1.1	<2.2	<1.1	<1.1	<1.1		<5.0	<2.3
MW-5	07/15/1993	7.5-9.5		82.0	<1.2	1.6	1.6	<2.4	<1.2	<1.2	16		14	3.2
MW-6	07/15/1993	5-7		89.0	<140	<140	180	310	<140	1,300	<140		42	15
MW-7	07/15/1993	5-7		83.0	<1.2	<1.2	<1.2	<2.4	<1.2	5.6	5.4		<5.0	110
MW-2P	07/15/1993	7.5-9.5		92.0	<130	320	470	1,800	<130	540	320		1,000	3.9
R 720 Generic					5.5	1,500	2,900	4,100	NA	NA	NA	100	100	50
R 746.06 Tabl R 746.06 Tabl				*****	8,500 1,100	38,000 NA	4,600 NA	42,000 NA	NA NA	86,000 NA	11,000 NA	NA NA	NA NA	NA NA

TABLE 1 SOIL LABORATORY ANALYTICAL RESULTS - (PVOC, Lead, GRO, DRO)

Mobil Service Station 05-LJJ Milwaukee, Wisconsin

Boring & Sample	Sample Date	Depth (ft bgs)	PID (IUs)	Percent Total Solids	Benzene (μg/kg)	Toluene (μg/kg)	Ethyl- benzene (μg/kg)	Total Xylenes (µg/kg)	MTBE (μg/kg)	1,2,4 TMBs (μg/kg)	1,3,5 TMBs (μg/kg)	DRO (mg/kg)	GRO (mg/kg)	Lead (mg/kg)
SB-5	07/15/1993	7.5-9.5		90.0	<1.1	1.1	<1.1	<2.2	<1.1	<1.1	<1.1		<5.0	1.7
B-1	05/11/2000	0-2	0.0											
		2-4	0.0	79.9	<31	<31	<31	<94	<31	<31	<31	<6.3	<6.3	13.00
	1	4-6	0.0											
	1	6-8	0.0											
	1	8-10	0.0											
		10-12	>1999											
	1	12-14	0.0											
		14-16	0.0											
B-2	5/10/2000	0-2	n/a											
		2-4	>1999	90.2	<28	<28	<28	<83	<28	<28	<28	67 H	<5.5	42
	1	4-6	1472											
		6-8 8-10	1607 1221											
		10-12	782											
B-3	5/11/2000	0-2	0.0			-								
D-0	3/11/2000	2-4	0.0	83.7	110	66	 88	215	 <30	239	 70			
	1	4-6	0.0					213		239	70		<6.0 	26
	1	6-8	0.0											
	1	8-10	>1999											
	1	10-12	>1999											
	1 1	12-14	110											
		14-16	23											
B-4	5/11/2000	0-2	0.0											
		2-4	0.0	83.9	<30	<30	<30	<89	<30	<30	<30		<6.0	12
		4-6	0.0											
	1	6-8	>1999	90.4	1,550	819	3,980	16,600	<155	6750	1,990		100	8.5
		8-10	>1999											
	[10-12	>1999											
		12-14	472											
		14-16	291											
NR 720 Generi			<u> </u>		5.5	1,500	2,900	4,100	NA	NA	NA	100	100	50
NR 746.06 Tabl					8,500	38,000	4,600	42,000	NA	86,000	11,000	NA	NA	NÁ
NR 746.06 Tab	le 2				1,100	NA	NA	NA	NA	NA	NA	NA	NA	NA

TABLE 1 SOIL LABORATORY ANALYTICAL RESULTS - (PVOC, Lead, GRO, DRO)

Mobil Service Station 05-LJJ Milwaukee, Wisconsin

Boring & Sample	Sample Date	Depth (ft bgs)	PID (IUs)	Percent Total Solids	Benzene (µg/kg)	Toluene (μg/kg)	Ethyl- benzene (µg/kg)	Total Xylenes (µg/kg)	MTBE (μg/kg)	1,2,4 TMBs (μg/kg)	1,3,5 TMBs (μg/kg)	DRO (mg/kg)	GRO (mg/kg)	Lead (mg/kg)
B-5	5/11/2000	0-2	0.0											
		2-4	0.0	78.8	<32	<32	<32	<95	<32	<32	<32		<6.3	7.6
		4-6	0.0											
		6-8	0.0											
		8-10	>1999											
	1	10-12	>1999											·
		12-14	212											
		14-16	78											
B-6	5/11/2000	0-2	0.0											
		2-4	0.0	80.0	<31	<31	<31	<94	<31	<31	<31	16	<6.2	36
		4-6	0.0											
		6-8	0.0											
		8-10	>1999	91.3	4,160	7,890	30,700	116,000	<548	66,800	17,500	164 H	1,200 H	9.0
		10-12	>1999											
		12-14	0.0											
		14-16	0.0											
MW-8	5/10/2000	0-2	n/a											
		2-4	75	92.1	<30	<30	<30	<89	<30	<30	<30		<6.0	15
		4-6	52											
	1	6-8	47											
		8-10	32											
		10-12	25											
		12-14	31											
		14-16	24											
R 720 Generi			<u> </u>		5.5	1,500	2,900	4,100	NA	NA	NA	100	100	50
R 746.06 Tabl					8,500	38,000	4,600	42,000	NA	86,000	11,000	NA	NA	NA
R 746.06 Tabl	le 2				1,100	NA	NA	NA	NA	NA	NA	NA	NA	NA

Note

---- Parameter not analyzed for compound indicated.

IUs - Instrument units in parts per million isobutylene

μg/kg - Micrograms per kilogram.

mg/kg - Milligrams per kilogram.

MTBE- Methyl tert-butyl ether.

TMBs - Trimethyl benzenes

DRO - Diesel Range Organics

GRO - Gasoline Range Organics

RCL - Residual Contaminant Level based on protection of groundwater.

H - Late eluting hydrocarbons present.

TABLE 3 GROUNDWATER LABORATORY ANALYTICAL RESULTS - (PVOC, Lead, DRO, and GRO) Mobil Service Station No. 05-LJJ Milwaukee, Wisconsin

Well Number	Sample Date	Benzene	Toluene	Ethyl- benzene	Total Xylenes	MTBE	Total Trimethyl- benzenes	Dissolved Lead	Total Lead	DRO	GRO
		(µg/L)	(µg/L)	(µg/L)	, (μg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)
MW-1	11/23/92	<1.0	<1.0	<1.0	<3.0	<1.0	<2.0	<3.0			<100.0
	8/11/93	<1.0	<1.0	<1.0	<2.0	<1.0	<2.0				<100.0
	11/20/97	<1.0	<1.0	<1.0	<3	<1.0	<2.0		<3.0	680	<100.0
	11/3/98	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
	5/18/99	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
	5/17/00	0.22	<0.20	<0.22	0.47	<0.16	<0.51		·		
	8/16/00	<0.13 <0.13	<0.20	<0.22	<0.23	<0.16	<0.51	-			
	11/7/00 2/6/01	<0.13	<0.20 	<0.22	<0.23	<0.16	<0.51				
	5/17/01	<0.13	<0.20	<0.22	 <0.23	 <0.16	<0.51			-	
	8/20/01	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
	11/13/01	<0.13	<0.20	<0.22	0.36	<0.16	<0.51				_
	2/28/02	<0.13	<0.20	<0.22	0.62	<0.16	<0.51				
						-					
MW-2	11/23/92	200	28	250	844	100	470	<3.0			4400
	8/11/93	1000	210	800	3000	66	780				11000
	11/20/97	770	53	110	443	39	229		<3.0	2100	4200
	11/3/98	410	50	200	690	<20M	498				
	DUP	520 1800	60	260	830	<37M	581				
	5/18/99 DUP	1600	620 520	680 590	2600 2100	<4.7M <6.5M	820 680				
	5/17/00	1100	180	630	2200	<8.0	1620				
	DUP	1100	180	620	2100	<8.0	1620				
	8/16/00										
	11/7/00	2000	170	680	2100	<3.2	1030				
	DUP	1900	170	640	1900	<1.6	930				
	2/6/01	420	26	110	230	<8.0	118	1.7			
	DUP	440	26	120	290	<8.0	150				ļ
	5/17/01	1700	170	500	1600	<5.5 M	700				
	DUP 8/20/01	1400 480	170 22	480 160	1500 440	<4.0 M	620				
	DUP	490	22	170	460	<7.2 M <8.0 M	191 196				
	11/13/01	270	11	110	240	<6.5 M	104				
	DUP	300	12	120	260	<7.3 M	115				
	2/28/02	190	3.5	46	52	24	34				
	DUP	260	3.8	70	54	24	40.4				
MW-3	11/23/92	<1.0	<1.0		<2.0	<1.0					4400.0
M W -3	i	<1.0		<1.0	<3.0	<1.0	<2.0	<3.0			<100.0
	8/11/93 11/20/97	79	<1.0 21	<1.0 88	<2.0	6.7	<7.2	- 1	-2.0	4000	<100.0
	11/3/98	13	5.1	30	116 110	<5 <3.4	<315.0 220		<3.0	1800	3300
	5/18/99	62	3.9	19	150	<4.5M	382.8				
	5/17/00	11	2.3	14	47	<1.9M	161.8				
	8/16/00	5.3	<2.0	7.4	41	19	220				
	11/7/00	6.5	1.0	6.3	43	<0.32	161.9				
	2/6/01	4.7	0.75	1.2	11	1.3	29.66	1.6			
	5/17/01	9.3	0.63	2.5	16	<1.0 M	85				
	8/20/01	10	1.0	3.9	33	<3.7	161.1				
	11/13/01	7.1	<0.20	1.6	4.6	<1.3	. 24				
	2/28/02	1.1	<0.20	0.72	1.8	<0.16	1.2				
MW-4	11/22/02	Z1 0	- 40	-10	-0.0	-4.0		40.0			4400.0
M W -4	11/23/92 8/11/93	<1.0 <1.0	<1.0 <1.0	<1.0 1.5	<3.0 2.9	<1.0 11	<2.0 9	<3.0			<100.0
	11/20/97	<1.0	<1.0	<1.0	<3.0	<1.0	<2.0	-	40	270	<100.0
	11/3/98	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51	[18	370	<100.0
	5/17/00				~0.25						
	8/16/00										
	11/7/00						weste				
	2/6/01										
	5/17/01										
	44.44										
MW-5	11/23/92		_								
	8/11/93	9.3	4.4	12	45	1.7	16.9	7.8			250
	11/20/97	29	<1.0	<1.0	15	8	<16		16	1200	260
i	11/3/98	6.5	0.59	59	16	3.6	31.36				
	5/18/99 5/17/00	7.9 81	5.6	130 130	220 97	4.2	139.7				
	8/16/00	4.4	3.0 <0.20	20	97 4.5	6.7 2.0	96.1 12				****
	11/7/00	4.4	<0.20	8.0	2.4	2.0	4.2				
	2/6/01	20	8.6	43	58	3.0	4.2 35,4	1.7			
	5/17/01	4.0	0.43	43	26	1.2	53.4 53.4				
l	8/20/01	0.37	<0.20	1.6	0.23	2.4	0.55				
İ	11/13/01	2.4	<0.20	4.2	0.43	2.1	1.4				
ļ	2/28/02	3.0	<0.20	4.3	2.4	2.2	2.5				
140 Standards			1000	700	40000		400	4.		, , , T	NI A
		5	1000	700	10000	60	480	15	NA	NA	NA

TABLE 3 GROUNDWATER LABORATORY ANALYTICAL RESULTS - (PVOC, Lead, DRO, and GRO) Mobil Service Station No. 05-LJJ

Milwaukee, Wisconsin

Well Number	Sample Date	Benzene	Toluene	Ethyl- benzene	Total Xylenes	МТВЕ	Total Trimethyl- benzenes	Dissolved Lead	Total Lead	DRO	GRO
	laite de la company	(µg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)	(µg/L)
MW-6	11/23/92										
	8/11/93	65	64	470	1800	<50	1140	7.8			11000
	11/20/97	370	51	78	318	37	134		59	1300	2700
	11/3/98	160	8.7	14	110	39	59.9				
	5/18/99	16	<1	<1	2.8	44	2.1				
	5/17/00	71	3.0	1.3	12	17	4.1				
	8/16/00	28	<4.0	<4.4	23	14	11				
	DUP	26	<4.0	<4.4	21	13	10				
	11/7/00	55	5.0	7.2	45	23	21.2				
	2/6/01	85	5.9	17	89	22	100	2.9			
	5/17/01	70	13.0	20	130	16	90				
	8/20/01	65	13.0	24	150	22	73				
	11/13/01	130	17.0	22	150	26	56.3				
	2/28/02	110	7.4	21	78	23	38.4				
MW-7	11/23/92										
	8/11/93	<1.0	<1.0	<1.0	<3.0	<1.0	<2.0	<2.0			<100.0
	11/20/97						****				
	11/3/98										
	5/17/00										
	11/7/00	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
	2/6/01	<0.13	<0.20	<0.22	0.27	<0.16	<0.51				
	5/17/01	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
	8/20/01	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
	11/13/01	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
	2/28/02	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
MW-8	5/17/00	41	<0.40	<0.44	1.2	<1.5 M	9.49				
	8/16/00	15	<0.20	<0.22	0.41	4.8	0.75				
	11/7/00	190	2.6	0.69	1.4	<0.16	3.6				
	2/6/01	170	4.5	3.4	9.4	<0.32	3.0	3.0			
	5/17/01	3.3	<0.10	<0.25	<0.25	0.86	0.20	i			
	8/20/01	120	0.56	<1.0	<1.0	<1.0	0.56				
	11/13/01	94	2.1	0.50	2.0	<0.50	1.6				
	2/28/02	56	1.7	0.68	6.1	6.1	0.84				
MW-2P	11/23/92										
	8/11/93	<1.0	1.3	3.3	7.7	7.7	13.2	<2.0			200
	11/20/97										
	11/3/98	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
	5/17/00										
	11/7/00	<0.13	0.21	<0.22	0.50	<0.16	0.25	- 1			
	2/6/01	<0.13	<0.20	<0.22	0.28	<0.16	<0.51	1.2			
	5/17/01	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
	8/20/01	<0.13	<0.20	<0.22	<0.23	<0.16	<0.51				
	11/13/01	0.16	<0.20	<0.22	0.28	<0.16	<0.51				
RW-1	11/20/97	24	9	3	306	<2.0	213		<3.0	4700	2800
	11/3/98						*****				
į	5/17/00										
RW-2	11/20/97	92	7	21	8	<1.0	<51		<3.0	1300	2100
l	11/3/98										
	5/17/00					-	·				
140 Standards								<u> </u>			·····
		5	1000	700	10000	60	480	15	NA	NA	NA
L		0.5	200	140	1000	12	96	1.5	NA	NA	NA

μg/I - Micrograms per liter. mg/I - Milligrams per liter. ---- Parameter not analyzed.

MTBE - Methyl tert-butyl ether.

GRO - Gasoline Range Organics.

DRO - Deisel Range Organics.

Total Trimethylbenzenes - 1,2,4-trimethylbenzenes and 1,3,5-trimethylbenzenes combined.

M - Matrix interference. ES - Enforcement Standard. PAL - Preventive Action Limit. N/A - No ES or PAL established.




TABLE 2 GROUNDWATER ELEVATIONS AND NATURAL ATTENUATION PARAMETERS
Mobil Service Station No. 05-LJJ Milwaukee, Wisconsin


WELL	DATE	TOC ELEVATION	TOTAL DEPTH	DEPTH TO GROUNDWATER	DEPTH TO PRODUCT	PRODUCT THICKNESS	GROUNDWATER ELEVATION	CONDUCTIVITY	TEMPERATURE	рΗ	DISSOLVED OXYGEN	ORP	NITRATE	SULFATE	DISSOLVED MANGANESE		DISSOLVED	TOTA
		(feet)	(feet bgs)	(feet below TOC)	(feet below TOC)	(feet)	(feet)	(µmho)	(°F)		(mg/L)	(mv)	(mg/L)	(mg/L)	(mg/L)	(mg/L)	(mg/L)	(mg/L
MW-1	11/23/92 8/11/93	631.08		9.43 8.18	_		621.65 622.90		_									T
j	9/16/93			8.34	_		622.74											
Ì	11/20/97	96.77	15.43	9.49	_		87.28		57.7		0.44							
i	11/3/98		15.43	9.29		_	87.48	2110	52.6			-100						
	5/18/99 5/17/00		15.42	8.57	-	_	88.20	3470	58.2	6.95	2.27	203	0.90	77	0.12	530	< 0.024	1.3
	8/16/00		15.42	9.32 8.98		_	87.45 87.79	2570 1061	52.3 62.2	6.01	1.37		<0.20	160	0.34	790	0.89	2.0
	11/7/00		15.42	9.04			87.73	1087	62.2 61.7	7.23 7.72	0,86 1,51		0.75 <0.50	77 170	0.23 0.24	620 460	0.87 0.20	0.80
	5/17/01		15.43	8.79			87.98	1128	52.2	7.16	0.89		<2.5	120	0.24	400	<0.042	0.36
	8/20/01		15.44	9.06	_		87.71	1181	60.9	6,60	1.09		<0.50	110	0.27	590	0.072	0.36
	11/13/01 2/28/02		15.44 15.44	9.33	_	- 1	87.44	4330	60.4	7.02	1.20		<0.50	120	0,60	610	0.28	1.4
			15.44	9.78	_	-	86.99	2590	50.2	7.51	1.16		0.76	72			1.40	
MW-2	11/23/92 8/11/93	630.68		9.08 8.10			621,60		_									
	9/16/93			8.27			622.58 622.41		_									
	11/20/97	97.19	15.21	9.47	_		87.72		57.7		0.42							
	11/3/98		15.28	9.19	. – 1		88.00	1815	55.7			-100	<0,055	39	0.053	560	7.7	13
	5/18/99		45.44	8.50	-	_	88.69	1939	57.9	6.48	0.74	-025	<0.055	75	0.093	650	13	15
i	5/17/00 8/16/00	i	15.11	9.22			87.97	2180	52.0	5.84	0.72		<0.20	59	0.058	610	10	35
	11/7/00		15.61	 8.97		_	88.22	1988	 59.9	7.66	0.85		 <0.50	44	_			
	2/6/01	į	15.25	9.44			87.75	1796	52.1	6.00	1.38		<1.0	44 100	0.062 0.071	510 410	8.0 7.4	20 23
ł	5/17/01		15.17	8.73		_	88.46	1721	51.6	4.88	0.69		<2.5	61	0.065	580	11	14
l	8/20/01		15.18	8.98	-	_·	88.21	1967	60.9	6.04	0.79		<0.50	59	0.10	560	8.3	15
1	11/13/01		15.18 15.18	9.17 9.58		_	88.02	4360	60,6	7.26	0.00		<0.50	56	0.081	550	7.9	14
			15.16	9.56		-	87.61	3810	49.1	7.62	1.00		1.4	81			7.7	
MW-3	11/23/92 8/11/93	631.71		9.86 8.69		-	621.85 623.02	_	_									
	9/16/93			8.91	_	_	623.02	;										
	11/20/97	97.24	15.74	9.98			87.26	_	58.5		0.55							
	11/3/98		15.75	9.67	_	-	87.57	897	57.9			-100	<0.055	40	. 0.11	420	0.75	3.0
-	5/18/99 5/17/00		15.74	15.70		_	81.54	1421	56.9	6.71	0.68	065	<0.055	58	0.20	330	1.0	1.9
	8/16/00		16.74	9.75 9.35	_	_	87.49 87.89	2350 1959	51.3 59.2	5.99 8.15	1.13		<0.20	110	0.19	420	2.5	2.9
- 1	11/7/00	1	16.72	9.44			87.80	1659	59.2 60.3	7.73	0,33 1.90		<0.50 <0.50	33 19	0.19 0.21	460 380	1.3 2.0	2.2
	2/6/01	l	15.78	9.81		_	87.43	1524	49.5	6.31	0,68		<2.5	50	0.21	480	1.2	2.1 5.4
	5/17/01		15.71	9.13			88.11	1927	51.3	6.85	0.93		<2.5	57	0.18	300	1.1	1.6
	8/20/01 11/13/01		15.74 15.74	9.48		_	87.76	1417	61.5	6.50	1.04		<0.50	34	0.27	490	2.1	2.5
	2/28/02		15.74	9.65 10.06			87.59 87.18	2310 2760	59.4 46.9	7.37 7.72	1.22		<0.50	33	0.10	390	0.69	8.0
			10.14					2700	40.9	1.12	1.66		1.3	54			0.84	
MW-4	11/23/92 8/11/93	632.76		10.50 10.47	_		622.26 622.29											
	9/16/93			10.56	_		622.20	_										
	11/20/97	98.29	16.69	10.98		_ I	87.31	_	57.6		0.86							
1	11/3/98 5/18/99		16.71	10.87	-		87.42	1189	52.8			049	<0.055	70	0.12	360	0.50	4.5
- 1	5/17/00			9.32 10.00		_	88.97 88.29		 54.3		0.75	183						
l	8/16/00			10.31		_	87.98		51.3 59.4		0.00 0.86	0.93						
- 1	11/7/00		16.69	10.49	_		87.80		58.6		0.97							
	5/17/01		16.70	9.93	-		88.36		50.9		0.72							
	8/20/01		16.70	10.57	-		87.72		57.7		0.79							
	11/13/01			10.53	****	-	87.76		59.0		1,05							
MW-5	8/11/93 9/16/93	631.37		8.62 8.86			622.75											
	9/16/93	97.09	15.28	8.86 10.09	_	_	622.51 87.00	-	60.4		0.38						•	
-	11/3/98	57.00	15.31	9.78			87.31	1100	56.4		0.38	-100	<0.055	120	0.94	500	0.90	5.0
- 1	5/18/99			8.77			88.32	2730	59.7	6.60	0.44	136	<0.055	230	0.93	490	2.2	3.9
- 1	5/17/00		15.29	9.79	-		87.30	1660	52.9	5.86	0.96		<0.20	88	0.85	710	2.5	3.9
1	8/16/00		15.21	9.51	-		87.58	1706	63.9	8.08							****	
	11/7/00 2/6/01		16.23 14.98	9.61 9.91		_	87.48 87.18	1125 1133	61.7 51,0	7.62 5.81	0.78 0.64		0.99 <0.50	92	0.66	420	0.50	3.4
	5/17/01		15.24	9.19		. =	87.90	1993	52,7	6.51	0.04		<2.5	120 190	0,82 1,00	450 400	0.75 1.50	7.1 5.3
	8/20/01	}	15.27	9.67	. –		87.42	1247	61.3	6.49	1.02		<0.50	190	1.60	500	1.30	6.0
l	11/13/01		15.27	9.84	-	. —	87.25	2740	60.4	7.18	0.36		<0.50	120	0.74	510	0.93	3.0
	2/28/02		15.27	10.17	*****		86.92	2510	48.9	7.50	1.36		1.7	96			0.74	

NOTES:
TOC - Top of casing.
bgs - Below ground surface.
ORP - Oxidation Reduction Potential, measured in millivolts (mv).
mg/L - Milligrams per liter.
---- Parameter not measured / analyzed.
- - Positive pressure inside well casing due to non-vented cap: this value is likely not representative of the static water elevation.
NI = Not installed

TABLE 2 GROUNDWATER ELEVATIONS AND NATURAL ATTENUATION PARAMETERS Mobil Service Station No. 05-LJJ Milwaukee, Wisconsin

WELL NUMBER	DATE	TOC ELEVATION	TOTAL DEPTH	DEPTH TO GROUNDWATER	DEPTH TO	PRODUCT	GROUNDWATER ELEVATION	CONDUCTIVITY	TEMPERATURE	рН	DISSOLVED OXYGEN	ORP	NITRATE	SULFATE	DISSOLVED MANGANESE	ALKALINITY	DISSOLVED	TOTAL
		(feet)	(feet bgs)			(feet)	(feet)	(µmho)	(°F)		(mg/L)	(mv)	(mg/L)	(mg/L)	(mg/L)	(mg/L)	(mg/L)	(mg/L
MW-6	11/23/92			NI			NI	_										
	8/11/93	631.32		8.77	_		622.55		_									
	9/16/93 11/20/97	97.04	45.00	8.88	_		622.44	_										
ł	11/3/98	97.04	15.90 15.91	10.02 9.78	_		87.02 87.26	1004	57.6		0.48	400						
	5/18/99		13.51	9.10	_		87.26 87.94	1664 1886	55.5 57.4	6.68	0.52	-100 042						
	5/17/00		15.75	9.85		_	87.19	2650	52.0	6.11	0.32							
- 1	8/16/00		15.75	9.38	****	_	87.66	1668	59.7	7.65	0.02		<0.50	34	0.24	450	5.9	29
1	11/7/00		15.82	9.48		_	87.56	1910	60.1	7.77	0.41							
	2/6/01		15.82	9.90			87.14	1776	52.0	5.00	0.51							
	5/17/01		15.85	9.21	_		87.83	1973	52.2	4.98	0.75							
	8/20/01 11/13/01		15.77	9.48	_		87,56	1534	61.9	6.05	1.04		l i					
	2/28/02		15.77 15.77	9.67 10.10			87.37 86.94	5000	59.0	7.29	0.05							
	2720702		15.77	10.10		_	00.94	3700	47.5	7.54	0.85							
MW-7	11/23/92			NI	****		NI	-										
	8/11/93	631.93		8.91	_		623.02	_										
	9/16/93			9.11			622.82	_	-									
	11/20/97	97.53	15.95	10.38	_		87.15		59.72		0.86							
	11/3/98 5/18/99		i	9.98	_		87.55											
	5/17/00		15.96	8.73 9.86			88.80 87.67				1.29	184	i I					
	8/16/00		15.80	9.60			87.93		52.0 62.6		0.76 0.56							
	11/7/00		15.95	9.75			87.78	1,168	61.2	7.28	0.56							
- 1	2/6/01		15.66	10.66			86.87	1,146	50.7	7.21	1.45							
l	5/17/01		15.96	9.28	****		88.25	1,201	50.5	7.11	1.35							
1	8/20/01		15.98	9.91			87.62	1,566	62.2	7.27	0.97							
1	11/13/01		15.98	10.06			87.47	2,120	60.3	6.86	1.24						-	
1	2/28/02		15.98	10.38			87.15	3,200	49.1	7.36	1.50							
MW-2P	11/23/92			NI NI			NI											
	8/11/93	630.86		31.68*		_	599.18											
	9/16/93			31.68*		_	599.18											
i	11/20/97		_	****	****	_												
	11/3/98		34.53	24.12		_	606.74	535	49.4			-036						
	5/18/99 5/17/00			24,79	-	_	606.07				1.32	071		****				
	8/16/00			24.84 24.36			606,02		54.7		2.56							
	11/7/00		35.52	23,41			606.50 607.45	628	55.4 55.6	9.23	2.23 2.38		<0.50	370	0.007		0.005	
	2/6/01		34.69	27.74			603.12	609	55.0	7.20	0.86		<0.50	380	0.087 0.092	90 120	0.025 <0.024	9.6 8.0
	5/17/01		34.52	25.07			605.79	746	55.4	7.30	1.68		1	360	0.030	100	0.20	7.1
	8/20/01		34.55	24.40			606.46	954	54.7	7.06	2.39		<0.50	450	0.90	140	0.69	6.0
	11/13/01			24.47		-	606.39	1,078	55.0	7.96	1.13		9.5	400	1.30	150	1.3	44.0
MW-8	5/17/00	96.48	14.67	8.31			88.17	2,000	54.0	7.75	107		.0.00					
	8/16/00	30.40	14.64	8.33			88.15	2,060 1,125	51.3 60.6	7.75 7.14	1.97 0.65		<0.20 0.90	.38 28	0.44 0.15	760 600	6.3	19
	11/7/00		14.62	8.36			88.12	1,743	59.0	7.85	0.03		<0.50	58	3.10	580	2.3 3.1	8.8 6.0
	2/6/01		14.37	8.51			87.97	1,258	49.3	6.21	0.86		<0.50	39	0.15	600	3.8	12.0
	5/17/01		14.65	7.87			88.61	1,674	50.2	6.72	0.86		<2.5	100	0.11	410	0.72	5.2
	8/20/01		14.65	8.42			88.06	1,886	59.5	6.21	0.93		<0.50	53	0.55	640	6.30	13.0
	11/13/01		14.65	8,53			87.95	3,190	58.6	7.16	0.62		<0.50	27	0.20	590	6.60	24.0
	2/28/02		14.65	8.78			87.70	3,250	47.8	7,46	1.14		2.10	17			7.10	
RW-1	11/20/97		15.67	8.72							•							
	11/3/98			7.98	_			_										
	5/18/99			7.23		_	_										****	
	5/17/00			7.94		_				_				_			_	
RW-2	11/20/97		15.55	9.88														<u> </u>
/XVV-2	11/3/98		15.55	9.88 8.51														
			I I			_	- !											
	5/18/99			/./6	_													
	5/18/99 5/17/00			7.76 8.59	_				_			_						

NOTES:
TOC - Top of casing.
bgs - Below ground surface.
ORP - Oxidation Reduction Potential, measured in millivolts (mv).
mg(L - Milligrams per liter.
---- Parameter not measured / analyzed.
-- Posameter not measured / analyzed.
-- Positive pressure inside well casing due to non-vented cap: this value is likely not representative of the static water elevation.
NI = Not installed



ExxonMobil
Refining and Supply Company
Downstream - Safety, Health & Environment
Environmental Remediation

Certified Mail #: 7002 2410 0004 2293 2440

December 1, 2003

ExonMobil
Refining & Supply

Lakeside Oil Company Mr. William Elliot 555 West Brown Deer Road Suite 200 Fox Point, Wisconsin 53217

Re: GIS Registry

Mobil Service Station 05-LJJ 4803 North Green Bay Road Milwaukee, Wisconsin

Dear Mr. Elliot:

On behalf of ExxonMobil Refinery and Supply Company (ExxonMobil), I am writing to notify you of recent revisions to the NR 700 rule series of the Wisconsin Administrative Code (WAC). Changes to the WAC became effective November 1, 2001 requiring certain properties to be listed on a geographic information system (GIS) Registry maintained by the Wisconsin Department of Natural Resources (WDNR). This recent rule change allows for closure of environmental remediation sites where natural attenuation is being used to complete groundwater cleanup without requiring groundwater use restrictions to be recorded with the property deed.

Groundwater at the property at 4803 North Green Bay Road, Milwaukee, Wisconsin (the Property) has been tested by ExxonMobil's consultants on a frequent basis, and has exhibited levels of benzene, and methyl-tert-butyl ether above the state groundwater enforcement standards found in chapter NR 140 of the WAC. However, the environmental consultants who have investigated this property have informed me that the area of dissolved-phase petroleum impacts to groundwater is stable or receding and will naturally degrade over time. Allowing natural attenuation to complete the cleanup at this site will meet the requirements for case closure that are found in chapter NR 726, WAC, and my consultant has requested that the Department of Commerce (the Department) accept natural attenuation as the final remedy for this site and grant case closure. Closure means that the Department will not be requiring any further investigation or cleanup action to be taken, other than the reliance on natural attenuation. Included as an attachment to this letter is a copy of the WDNR's fact sheet describing the use of natural attenuation as a final remedy (Publication #RR-671).

The Department will not review my closure request for at least 30 days after the date of this letter. As the owner of the Property, you may contact the Department to provide any technical information that indicates closure should not be granted for this site. If you would like to submit any information relevant to this closure request to the Department, you should mail that information to: Ms. Monica Weiss, Hydrogeologist, Wisconsin Department of Commerce, Environmental and Regulatory Services Division, 101 West Pleasant Street, Suite 100A, Milwaukee, Wisconsin 53212.

If this case is closed, all properties within the area where groundwater quality exceeds NR 140 groundwater enforcement standards will be listed on the WDNR's GIS Registry of Closed Remediation Sites. The information on the GIS Registry includes maps showing the location of properties in Wisconsin where groundwater quality above chapter NR 140 standards was found at the time that the case was closed. This GIS Registry will be available to the general public on the

WDNR's internal web site. I have enclosed with this letter the legal description of the property. Please review this legal description and notify me within the next 30 days if the legal description is incorrect.

The GIS registry will be used by the WDNR to make sure wells are properly installed in Wisconsin. Should you or any subsequent property owner wish to construct or reconstruct a well, special well construction standards may be necessary to protect the well from groundwater above NR 140 enforcement standards. Any well driller who proposes to construct a well on the Property in the future will first need to call the Digger's Hotline (1-800-242-8511) if the Property is located outside of the service area of a municipally owned water system. If the Property is located within the designated service area of a municipally owned water system, the driller will need to contact the Drinking Water program within the WDNR. Either way, the WDNR will then contact the well driller to advise if there is a need for special well construction standards.

It is my understanding that Lakeside Oil Company, purchased the Property from ExxonMobil during January 2003. Neither you nor any subsequent owner of the Property will be held responsible for investigation or cleanup of impacts to groundwater caused by activities that occurred at the property prior to 2003, as long as you and any subsequent owners comply with the requirement of section 292.13, Wisconsin Statutes, including allowing access to you property for environmental investigation or cleanup if access is required. For further information on the requirements of Section 292.13, Wisconsin Statutes, you may call 1-800-367-6076 to obtain a copy of the WDNR's publication #RR-589, Fact Sheet 10: Guidance for Dealing with Properties Affected by Off-Site Contamination. There are no costs to you for the closure or for the GIS Registry.

Once the Department makes a decision on my closure request, it will be documented in a letter. I will forward you a copy of the closure letter for your information. You may also obtain a copy of this letter by writing to the agency address given above, or by accessing the DNR GIS Registry of Closed Remediation Sites on the internet at www.dnr.state.wi.us/org/at/et/geo/gwur. A copy of the closure letter will be included as part of the site file on the GIS Registry of Closed Remediation Sites.

Should you have any questions regarding this correspondence, please do not hesitate to contact me at (815) 521-7369, or you may contact Ms. Monica Weiss of the Wisconsin Department of Commerce at (414)-220-5361.

Sincerely,

Jeffrey A. Johnson Territory Manager

ExxonMobil Oil Corporation

Attachments:

1. WDNR Factsheet (Publication #RR-671)

2. Legal Description of the Property

Cynthin M. Drowns FOR

cc: Cynthia Draves, Handex of Wisconsin

Monica Weiss, Wisconsin Department of Commerce

Legal Description 1708 West Hampton Avenue a/k/a 4803 North Green Bay Avenue Milwaukee, Wisconsin

The East 51.35 feet of the West 191.35 feet of Lot 5, except the South 22 feet thereof, in Block 1, Lincoln Park Annex, being a part of the Southeast Quarter of Section 31, in Township 8 North, Range 22 East, in the City of Milwaukee, Milwaukee County, State of Wisconsin.

Also Lot 5, in Block 1, in Lincoln Park Annex, being a part of the Southeast Quarter of Section 31, Township 8 North, Range 22 East, in the City of Milwaukee, except the West 191.35 feet thereof.

Also part of the Southeast Quarter of Section 31, in Township 8 North, Range 22 East, in the City of Milwaukee, bounded and described as follows, to wit: Commencing at a point in the South line 1227.35 feet East of the Southwest corner of the Southeast Quarter of Section 31, running thence East on and along the South line of the Southeast Quarter of Section 31, 208 feet to a point at the intersection of the center line of North Green Bay Avenue with the South line of said quarter section; thence North 10%%d43' West on and along the center line of North Green Bay Avenue 140.46 feet to a point; thence West on and along a line which is 138 feet North of and parallel with the South line of said quarter section 182.81 feet to a point; thence South 138 feet to the place of beginning, excepting thereform the following described premises:

- (1) The South 33 feet thereof lying Westerly of the Westerly line of North Green Bay Avenue:
- (2) That portion of said premises bounded an described as follows: Commencing at a point in the South line of the Southeast Quarter of Section 31, in the Township 8 North, Range 22 East, said point lying 1227.35 feet East of the Southwest corner of said quarter section; running North and parallel to the West line of said quarter section 33.00 feet to a point in the North line of West Hampton Avenue, said point being the point of beginning of the land to be described; thence North on a line parallel to the West line of said quarter section, 22.00 feet to a point, which is 55.00 feet North of and measured at right angles to eth South line of said quarter section; thence East on a line parallel to the South line of said quarter section 152.45 feet t to a point; thence Northeasterly on a line15.32 feet to a point in the Westerly line of North Green Bay Avenue, said point being 34.49 feet Northwesterly of the North line of West Hampton Avenue and measured along the Westerly line of North Green Bay Avenue; thence Southeasterly along said Westerly line of North Green Bay Avenue; thence Southeasterly along said Westerly line of North Green Bay Avenue; thence Southeasterly along said Westerly line of North Green Bay Avenue 34.39 feet to a point in said North Line of West Hampton Avenue; thence West along said North line of West Hampton Avenue 168.47 feet to the point beginning.
- (3) That portion of said premises lying within the limits of North Green Bay Avenue.

ExxonMobil
Refining and Supply Company
Downstream - Safety, Health & Environment
Environmental Remediation

Certified Mail #: 7002 0510 0000 2287 9546

December 1, 2003

ExonMobil
Refining & Supply

Ms. Vawn Peufateri Current Dealer - Mobil 05-LJJ 1710 West Hampton Avenue Milwaukee, Wisconsin 53209

Re: GIS Registry

Mobil Service Station 05-LJJ 1710 West Hampton Avenue Milwaukee, Wisconsin 53209 Commerce #: 53209-5730-30 WDNR BRRTS #: 03-41-003691

Dear Ms. Peufateri:

On behalf of ExxonMobil Refinery and Supply Company (ExxonMobil), I am writing to notify you of recent revisions to the NR 700 rule series of the Wisconsin Administrative Code (WAC). Changes to the WAC became effective November 1, 2001 requiring certain properties to be listed on a geographic information system (GIS) Registry maintained by the Wisconsin Department of Natural Resources (WDNR). This recent rule change allows for closure of environmental remediation sites where natural attenuation is being used to complete groundwater cleanup without requiring groundwater use restrictions to be recorded with the property deed.

Groundwater at the property at 1710 West Hampton Avenue, Milwaukee, Wisconsin (the Property) has been tested by ExxonMobil's consultants on a frequent basis, and has exhibited levels of benzene, and methyl-tert-butyl ether above the state groundwater enforcement standards found in chapter NR 140 of the WAC. However, the environmental consultants who have investigated this property have informed me that the area of dissolved-phase petroleum impacts to groundwater is stable or receding and will naturally degrade over time. Allowing natural attenuation to complete the cleanup at this site will meet the requirements for case closure that are found in chapter NR 726, WAC, and my consultant has requested that the Department of Commerce (the Department) accept natural attenuation as the final remedy for this site and grant case closure. Closure means that the Department will not be requiring any further investigation or cleanup action to be taken, other than the reliance on natural attenuation. Included as an attachment to this letter is a copy of the WDNR's fact sheet describing the use of natural attenuation as a final remedy (Publication #RR-671).

If this case is closed, all properties within the area where groundwater quality exceeds NR 140 groundwater enforcement standards will be listed on the WDNR's GIS Registry of Closed Remediation Sites. The information on the GIS Registry includes maps showing the location of properties in Wisconsin where groundwater quality above chapter NR 140 standards was found at the time that the case was closed. This GIS Registry will be available to the public on the WDNR's internal web site.

The GIS registry will be used by the WDNR to make sure wells are properly installed in Wisconsin. Should you or any subsequent property owner wish to construct or reconstruct a well, special well construction standards may be necessary to protect the well from groundwater above NR 140

enforcement standards. Any well driller who proposes to construct a well on the Property in the future will first need to call the Digger's Hotline (1-800-242-8511) if the Property is located outside of the service area of a municipally owned water system. If the Property is located within the designated service area of a municipally owned water system, the driller will need to contact the Drinking Water program within the WDNR. Either way, the WDNR will then contact the well driller to advise if there is a need for special well construction standards.

Neither you nor any subsequent owner of the Property will be held responsible for investigation or cleanup of impacts to groundwater caused by activities that occurred at the property prior to 2003, as long as you and any subsequent owners comply with the requirement of section 292.13, Wisconsin Statutes, including allowing access to you property for environmental investigation or cleanup if access is required. For further information on the requirements of Section 292.13, Wisconsin Statutes, you may call 1-800-367-6076 to obtain a copy of the WDNR's publication #RR-589, Fact Sheet 10: Guidance for Dealing with Properties Affected by Off-Site Contamination. There are no costs to you for the closure or for the GIS Registry.

Once the Department makes a decision on my closure request, it will be documented in a letter. I will forward you a copy of the closure letter for your information. You may also obtain a copy of this letter by writing to the agency address given above, or by accessing the DNR GIS Registry of Closed Remediation Sites on the internet at www.dnr.state.wi.us/org/at/et/geo/gwur. A copy of the closure letter will be included as part of the site file on the GIS Registry of Closed Remediation Sites.

Should you have any questions regarding this correspondence, please do not hesitate to contact me at (815) 521-7369, or you may contact Ms. Monica Weis of the Wisconsin Department of Commerce at (414)-220-5361.

Sincerely,

Jeffrey A. Johnson Territory Manager

ExxonMobil Oil Corporation

Attachments: WDNR Fact Sheet Publication RR-671

cc: Cynthia Draves, Handex of Wisconsin

Monica Weis, Wisconsin Department of Commerce

ExxonMobil
Refining and Supply Company
Downstream - Safety, Health & Environment
Environmental Remediation

Certified Mail #: 7002 0510 0000 2287 9508

December 1, 2003

ExonMobil
Refining & Supply

Mr. Roy Nelson 1830 West Hampton Avenue Milwaukee, Wisconsin 53209

Re: GIS Registry

Mobil Service Station 05-LJJ/Apartment Building 4803/4827 North Green Bay Road

Milwaukee, Wisconsin 53209 Commerce #: 53209-5730-30 WDNR BRRTS #: 03-41-003691

Dear Mr. Nelson:

On behalf of ExxonMobil Refinery and Supply Company (ExxonMobil), I am writing to notify you of recent revisions to the NR 700 rule series of the Wisconsin Administrative Code (WAC). Changes to the WAC became effective November 1, 2001 requiring certain properties to be listed on a geographic information system (GIS) Registry maintained by the Wisconsin Department of Natural Resources (WDNR). This recent rule change allows for closure of environmental remediation sites where natural attenuation is being used to complete groundwater cleanup without requiring groundwater use restrictions to be recorded with the property deed.

Groundwater at the property at 4827 North Green Bay Road, Milwaukee, Wisconsin (the Property) has been tested by ExxonMobil's consultants on a frequent basis, and has exhibited levels of benzene, and methyl-tert-butyl ether above the state groundwater enforcement standards found in chapter NR 140 of the WAC. However, the environmental consultants who have investigated this property have informed me that the area of dissolved-phase petroleum impacts to groundwater is stable or receding and will naturally degrade over time. Allowing natural attenuation to complete the cleanup at this site will meet the requirements for case closure that are found in chapter NR 726, WAC, and my consultant has requested that the Department of Commerce (the Department) accept natural attenuation as the final remedy for this site and grant case closure. Closure means that the Department will not be requiring any further investigation or cleanup action to be taken, other than the reliance on natural attenuation. Included as an attachment to this letter is a copy of the WDNR's fact sheet describing the use of natural attenuation as a final remedy (Publication #RR-671).

If this case is closed, all properties within the area where groundwater quality exceeds NR 140 groundwater enforcement standards will be listed on the WDNR's GIS Registry of Closed Remediation Sites. The information on the GIS Registry includes maps showing the location of properties in Wisconsin where groundwater quality above chapter NR 140 standards was found at the time that the case was closed. This GIS Registry will be available to the public on the WDNR's internal web site.

The GIS registry will be used by the WDNR to make sure wells are properly installed in Wisconsin. Should you or any subsequent property owner wish to construct or reconstruct a well, special well construction standards may be necessary to protect the well from groundwater above NR 140 enforcement standards. Any well driller who proposes to construct a well on the Property in the future will first need to call the Digger's Hotline (1-800-242-8511) if the Property is located outside of the

service area of a municipally owned water system. If the Property is located within the designated service area of a municipally owned water system, the driller will need to contact the Drinking Water program within the WDNR. Either way, the WDNR will then contact the well driller to advise if there is a need for special well construction standards.

Neither you nor any subsequent owner of the Property will be held responsible for investigation or cleanup of impacts to groundwater caused by activities that occurred at the property prior to 2003, as long as you and any subsequent owners comply with the requirement of section 292.13, Wisconsin Statutes, including allowing access to you property for environmental investigation or cleanup if access is required. For further information on the requirements of Section 292.13, Wisconsin Statutes, you may call 1-800-367-6076 to obtain a copy of the WDNR's publication #RR-589, Fact Sheet 10: Guidance for Dealing with Properties Affected by Off-Site Contamination. There are no costs to you for the closure or for the GIS Registry.

Once the Department makes a decision on my closure request, it will be documented in a letter. I will forward you a copy of the closure letter for your information. You may also obtain a copy of this letter by writing to the agency address given above, or by accessing the DNR GIS Registry of Closed Remediation Sites on the internet at www.dnr.state.wi.us/org/at/et/geo/gwur. A copy of the closure letter will be included as part of the site file on the GIS Registry of Closed Remediation Sites.

Should you have any questions regarding this correspondence, please do not hesitate to contact me at (815) 521-7369, or you may contact Ms. Monica Weis of the Wisconsin Department of Commerce at (414)-220-5361.

Sincerely,

cc:

Jeffrey A. Johnson

Territory Manager ExxonMobil Oil Corporation

.

inthie Movers For

Attachments: WDNR Fact Sheet Publication RR-671

Cynthia Draves, Handex of Wisconsin

Monica Weis, Wisconsin Department of Commerce



Certified Mail #: 7002 2410 0004 2293 2464

November 21, 2003

City Clerk of Milwaukee 200 East Wells Street Milwaukee, Wisconsin 53202

Re:

Notification of Potential Petroleum Impacts within ROW Adjacent to:

Mobil Service Station 05-LJJ 4803 North Green Bay Avenue Milwaukee, Wisconsin Commerce #53209-5730-30 WDNR BRRTS # 03-41-003691

Dear Sir or Madam:

Handex of Wisconsin (Handex) has prepared this letter on behalf of ExxonMobil Refining and Supply Company (ExxonMobil) to notify the City of Milwaukee (the City) that residual petroleum impacts to groundwater may be present within the right-of-ways (ROWs) located adjacent to the above-referenced property. This notification is required by the State of Wisconsin as a condition of closure for the environmental case file associated with the service station.

Residual groundwater impacts may be present within the North Green Bay Road (US Highway 57) ROW located adjacent and to the east of the service station. As of February 2002, benzene was reported at concentrations of 190, 110 and 56 micrograms per liter (μ g/L), respectively in monitoring wells MW-2, MW-6 and MW-8 located west of the North Green Bay Avenue ROW. A site map with groundwater concentrations is included for your reference.

Should you have any questions, or require additional information, please feel free to contact the undersigned in writing at the letterhead address, or by telephone at (262) 641-9011, extension 103.

Sincerely.

Handex of Wisconsin

Cynthia M. Draves Project Hydrogeologist

cc:

Jeff Johnson, ExxonMobil Refining and Supply Company

Gary Mick, Milwaukee County (DPW) (Certified Mail #: 7002 2410 0004 2293 2471)

Keith Ponath, Milwaukee County (Highway Operations)

Draves, Cynthia

From:

Draves, Cynthia

Sent:

Friday, November 21, 2003 10:36 AM

To:

'sharlene.tebeest@dot.state.wi.us'

Subject:

Notification of Contamination with Right-of-Way

Dear Ms. Te Beest,

This correspondence is to notify the WDOT of a site closure request being made for former Mobil service station, Mobil 05-LJJ, located at 4803 North Green Bay Road (US Highway 57), Milwaukee, Wisconsin. In the past, this site has also been referenced as 1710 West Hampton Avenue, Milwaukee, Wisconsin. As requested, I'm providing this notification via email. In addition to the notification of the closure request currently in progress, this correspondence is to notify the WDOT of petroleum contaminated groundwater, and possibly soil, that may extend beneath the North Green Bay Road (Highway 57) ROW adjacent to the east of the previously mentioned site. Attached you will find a groundwater and soil figure in 'pdf' format, and a completed notification document.








LJJ-Soil-Fig.p LJJ-GW-Fig. LJJROWNOT df (49 KB) pdf (52 KB) .DOC (29 KB)


Please feel free to call or email if you have any questions regarding this email or the attachments.

SINCERELY.

CYNTHIA M. DRAVES
PROJECT HYDROGEOLOGIST

HANDEX OF WISCONSIN 16940 VICTOR RD. NEW BERLIN, WI 53151 TEL. (262) 641-9011 EXT. 103 FAX (262) 641-9987 Email: cdraves@handexmail.com





Notification of Potential Contamination within the Right of Way

County: Milwaukee County

Highway: 57

Site Name: Mobil Service Station 05-LJJ

Site Address: 4803 North Green Bay Avenue (Highway 57)

BRRTS Number: 03-41-003691 PECFA Number: 53209-5730-30

FID Number: 241405230

Responsible Party's Name: ExxonMobil Oil Corporation

Responsible Party's Address: Joliet Refinery, PO Box 874, Joliet, IL 60434

Consulting Firm: Handex of Wisconsin Consultant Contact: Cynthia M. Draves

Consultant Address: 16940 West Victor Road, New Berlin, WI 53151 Consultant Phone, Fax and E-mail: 262-641-9011; ext. 103, 262-641-9987;

cdraves@handexmail.com

Soil contamination? Yes/no: YES

Depth to contaminated soil: Below 4 feet

Vertical extent of contaminated soil: Approximately 10 feet

Groundwater contamination? Yes/no: On-property yes, potentially in ROW

Depth to water table: Approximately 7-10 feet

Describe the type(s) of contamination present: Petroleum Volatile Organic Compounds (PVOCs)

Brief summary of cleanup activity: Liquid-phase petroleum hydrocarbon recovery, excavation, and natural attenuation.

Attach a current plume map for groundwater contamination: See attached. Attach a current plume map for soil contamination: See attached.

Draves, Cynthia

From: TeBeest, Sharlene [sharlene.tebeest@dot.state.wi.us]

Sent: Friday, November 21, 2003 2:05 PM

To: 'Draves, Cynthia'

Subject: RE: Notification of Contamination with Right-of-Way

Thank you Cynthia! I've received your notification.

Shar

Shar Te Beest
Hazardous Materials Specialist /District 1 Liaison
Wisconsin Department of Transportation
Bureau of Equity and Environmental Services
Phone (608) 266-1476; Fax (608) 266-7818
e-mail: sharlene.tebeest@dot.state.wi.us

----Original Message----

From: Draves, Cynthia [mailto:CDraves@handexmail.com]

Sent: Friday, November 21, 2003 10:36 AM **To:** 'sharlene.tebeest@dot.state.wi.us'

Subject: Notification of Contamination with Right-of-Way

Dear Ms. Te Beest,

This correspondence is to notify the WDOT of a site closure request being made for former Mobil service station, Mobil 05-LJJ, located at 4803 North Green Bay Road (US Highway 57), Milwaukee, Wisconsin. In the past, this site has also been referenced as 1710 West Hampton Avenue, Milwaukee, Wisconsin. As requested, I'm providing this notification via email. In addition to the notification of the closure request currently in progress, this correspondence is to notify the WDOT of petroleum contaminated groundwater, and possibly soil, that may extend beneath the North Green Bay Road (Highway 57) ROW adjacent to the east of the previously mentioned site. Attached you will find a groundwater and soil figure in 'pdf' format, and a completed notification document.

<<LJJ-Soil-Fig.pdf>> <<LJJ-GW-Fig.pdf>> <<LJJROWNOT.DOC>>

Please feel free to call or email if you have any questions regarding this email or the attachments.

SINCERELY,

CYNTHIA M. DRAVES

PROJECT HYDROGEOLOGIST

HANDEX OF WISCONSIN

16940 VICTOR RD.

NEW BERLIN, WI 53151

TEL. (262) 641-9011 EXT. 103

Fax (262) 641-9987

Email: cdraves@handexmail.com